

Stationary Screws w/ washers

A - (2): 8-32 x 5/16"

B - (2): 8-32 x 7/16"

C - (2): 10-32 x 9/16"

D - (2): 10-32 x 9/16"

E - (2): 10-32 x 9/16"

F - (2): 1/4-20 x 5/8"

F1 - (2): 1/4"-20 x 5/8"

F2 - (2): 1/4-20 x 3/4"

F3 - (2): 1/4-20 x 7/8"

Driven Cutter Screws

A - (2): 10-24 x 3/4"

B - (2): 1/4-20 x 1"

C - (2): 5/16-18 x 1-1/4"

D - (2): 3/8 x 1-1/4"

E - (2): 3/8 x 1-1/4"

F - (2): 3/8-16 x 2" w/ lock nut

F1 - (2): 3/8-16 x 2" w/ lock nut

F2 - (2): 3/8-16 x 2" w/ lock nut

F3 - (2): 3/8-16 x 2" w/ lock nut

HB Screws w/ washers

#A, #AA, #1, #2A, #2B – (3): 5/16 x 3/8"

#2 – (3): 5/16 x 7/8"

#3, #3A – (3) 3/8 x 7/8"

#4 – (2) 3/8 x 1", (1) 3/8 x 1-1/4"

#5, #5A – (2) 3/8 x 1-1/4", (2) 3/8 x 1-1/2"